

Your Cost:

### Final Testing and Completion Report (SV3)

\*\* Home has not been verified complete. Rebates pending verification.

Site Walk Date: 2012-03-09

Cost of Services: \$1,150.00 **Building Code** MN Code **Energy Rebate:** \$150.00 File Number #16600 Site Walk Date Rater Rebate: \$250.00 2012-03-09

\$750.00\*\*





#### Home Builder 6712 West River Rd The Chuba Co.

Brooklyn Center, MN 55430

xx, MN 55xxx

#### Model

Custom

Type: Single-family detached

Size: 3882 ft<sup>2</sup>

#### Meets ENERGY STAR Requirements NO

Checklists Completed Checklists Signed Meets Testing Standards

No No Yes

**HERS Index** 



RESNET Ratings provide a relative energy use index called the HERS Index, which represents the home's energy usage as a percentage of the energy usage of the "American Standard Building."

Beats 2004 IECC standard by

83.46%

7

TBC Failures need correcting

Issues could use improvement

Exceptional building practices identified

Insulation Feature	es

Worst Insulation III/NR Grade Rim Grade: III/NR R = 44.0 (Grade III/NR) Ceiling Flat Vaulted Ceiling R = 38.0Above Grade Walls R = 0.0 (Grade III/NR) Foundation Walls n/a (Grade III/NR) Framed Floors n/a (Grade III/NR) R = 15.0 Edge, 15.0 Under (Grade Slab

Duct

Window U = 0.300, SHGC = 0.300

	Blower	Door	Test F	Results
Tested CFM50				

667 CFM50/ft<sup>2</sup> surface area 0.09 CFM50/ft<sup>2</sup> floor area 0.17 ACH50 1.01

#### **Ventilation Flow Test Results**

Target Flow (CFM)		Unknown
Actual Flow (CFM)		
Rated Flow (CFM)		150.0
Duct Leakage to Outside		15

	Heat	Cooling	Hot Water	Ventilation	Thermostat
Efficiency	(AFUE)	(SEER)			
Brand / Make	Geo Comfort	Geo Comfort	Navien	Venmar	Honeywell
Model	gxt048a11mm1css	gxt048a11mm1css	nr-240ang	Venmar	Honeywell
Size	BTU	BTU			
Serial Number	m10090458		9545-20100320-3016		



## Final Testing and Completion Report (SV3)

\*\* Home has not been verified complete. Rebates pending verification.
Site Walk Date: 2012-03-09



### Opportunities for Quality Improvement

Items and pictures listed in this section do not require corrective action. These items are opportunities for additional improvement.

## 1

#### Air leakage pathways

Pictured are the doors on the upper level. The door makes insufficient contact with the weatherstripping even when locked. Unintentional air leakage pathways can result in unconditioned air moving through enclosed building cavities leading to reduced insulation effective R-value, building durability, uneven interior surface temperatures, structural air leakage, occupant discomfort, and high utility costs.






Figure 1.1

Figure 1.2

## 2

#### Electrical box leakage

Unsealed electrical boxes can lead to durability issues, uneven interior surface temperatures, drafts, and occupant discomfort. Foam wiring penetrations and seal the vapor/air barrier to boxes.



Figure 2.1



# Final Testing and Completion Report (SV3) \*\* Home has not been verified complete. Rebates pending verification.

Site Walk Date: 2012-03-09

#### Top plate penetrations

Penetrations in framing can lead to uneven interior surface temperatures and unconditioned air leakage into the structure. Seal penetrations before insulation and vapor retarder are installed.



Figure 3.1




Figure 3.2



Figure 3.3



### Final Testing and Completion Report (SV3)

\*\* Home has not been verified complete. Rebates pending verification.

Site Walk Date: 2012-03-09



### **Exceptional Building Practices**

The following items are demonstrative of exceptional construction practices and details. Not only have you exceeded standard building practices, it has been done so in an exceptional manner.

4

#### Window/door trim leakage

Incomplete sealing around doors and windows allows unconditioned air leakage to structure and can affect occupant comfort. Use low expansion foam around window and door frames to seal and insulate.






Figure 4.1

Figure 4.2

5

#### Recessed light leakage to attic

Recessed light leakage allows air to move between conditioned and unconditioned spaces, degrades insulation performance, and can lead to occupant comfort issues. Air seal gaps in recessed lights with high temperature sealant, and caulk or foam between the can and drywall or install an airtight box over recessed cans.




Figure 5.1




Figure 5.2



### Final Testing and Completion Report (SV3)

\*\* Home has not been verified complete. Rebates pending verification.
Site Walk Date: 2012-03-09

### Confidentiality

Residential Science Resources, LLC respects the privacy of The Chuba Co. and will keep all of this information confidential and not disclose this or any other information without expressed written consent. Thank you for the opportunity to assist you in the construction of your homes.

Sincerely, Josh Heller email: josh.heller@residentialscience.com phone: 612-990-6187 Residential Science Resources, LLC

Residential Science Resources, LLC is an independent building performance testing and certification company following RESNET guidelines. RESNET sets the standards of quality for the building energy performance certification industry (Home Energy Rating System – HERS Rating). The EPA requires homes to meet its strict standards for the ENERGY STAR® certification following RESNET guidelines.