





ENERCEPT, INC.
3100 9th AVE SE
WATERTOWN, SD 57201
PHONE: (605) 882-2222
FAX: (605) 882-2753
www.enercept.com

- REVISIONS:
- REVISION A 09-20-2016:
Adjusted upper window header heights.
Removed a section of SIP's from upper level. Adjusted window R.O.s. Adjusted overhang of upper roof, lower section. Added bracker in upper roof, lower section for on-site nailing. Adjusted upper truss/SIP roof pitch to 5/12. Adjusted upper truss heel height from 4 7/8" to 5". Changed #2x6 hold downs from HDx5 to HDx8. (BLS)
 - REVISION B 9-27-2016
Made revision adjustments per Wendel's redlines.Changed lower window sizes. Added note to interior wall framing detail. Showing trusses on Roof Panel Layout sheet. Updated structure sections. (BLS)
 - REVISION C 10-3-2016
Added additional vertical chases. (BLS)
 - REVISION D 10-7-2016
Updated connection details of trusses to upper level panels. (BLS)
 - REVISION E 10-19-2016
Adjusted upper level hold-down locations. (BLS)
 - REVISION F 10-26-2016
Adjusted section details. (BLS)
 - REVISION G 10-28-2016
Adjusted window R.O.s. (BLS)
 - REVISION H 11-3-2016
Revised section details (BLS)

JLC OFFICE BUILDING		3D VIEWS
SEND DRAWINGS TO:	BUILDER INFORMATION:	
SCALE: AS NOTED		
DRAWN BY: BLS		
DATE: 9/6/2016		
PROJECT NUMBER: 69276		
SHEET: 6 OF 14		