4895 S 80 E

WOLCOTTVILLE, IN 46795

PETE'S CONSTRUCTION

THIS HOME IS CERTIFIED TO MEET THE 2009 INTERNATIONAL ENERGY CONSERVATION CODE

Building Features

Ceiling Attic, R-40

Above Grade Walls R-28

Foundation Walls R-14

Framed Floor R-38

Organization:

Slab R-0.0 Perimeter, R-0.0 Under

Infiltration 1638 CFM50 (2.26 ACH50)

Window U-Value: 0.33, SHGC: 0.17

Duct Supply R-0.0, Return R-0.0

Duct Leakage to Outside 20.0 CFM @ 25 Pa

Total Duct Leakage N/A

Heating Furnace • Natural Gas • 96 AFUE

Cooling Air Conditioner • Electric • 14 SEER

Water Heating Water Heater • Natural Gas • 0.72 Energy Factor

As a 3rd party extension of the code jurisdiction utilizing these reports, I certify that this energy code compliance document has been created in accordance with the requirements of Chapter 4 of the adopted International Energy Conservation Code based on Climate Zone 5. If rating is Projected, I certify that the building design described herein is consistent with the building plans, specifications, and other calculations submitted with the permit application. If rating is Confirmed, I certify that the address referenced above has been inspected/tested and that the mandatory provisions of the IECC have been installed to meet or exceed the intent of the IECC or will be verified as such by another party.

Name: Travis Marker

Energy Diagnostics Rater

Signature:

Digitally signed:

10/8/18 at 3:13 PM

Ekotrope RATER - Version 2.2.5.2022

No version of this software has been reviewed or approved by ICC or its affiliates.

The 2009 International Energy Conservation Code is a registered trademark of the International Code Council, Inc. (ICC').

This software is a RESNET Accredited HERS Rating Tool.

IECC 2009 Performance Compliance

Property 4895 S 80 E WOLCOTTVILLE, IN 46795

4895 S 80 E 105634 18 Organization

Energy Diagnostics Rater Travis Marker

ravis Marker Inspection Status
Confirmed by field test

Builder

PETE'S CONSTRUCTION



		Annual En	eray Cost			
Design			07	IECC 2009	As E	esigned
Heating Cooling Water Heating				Performance \$1,713 \$136 \$181		\$1,686 \$100 \$181
SubTotal - Used to determine	comp	liance		\$2,030		\$1,967
ights & Appliances Onsite generation				\$733 \$0		\$733 \$0
Total				\$2,763		\$2,700
405.3 Performance-based compliance passes by 3.1%	②	402.4.2.1 Air Leakage Testing	⊘	402.5 Area-weighted average fenestration SHGC	⊘	
402.5 Area-weighted average fenestration U-Factor		403.2.2 Duct Testing		Mandatory Checklist		
o-i actor						

Design exceeds requirements for IECC 2009 Performance compliance by 3.1%.

As a 3rd party extension of the code jurisdiction utilizing these reports, I certify that this energy code compliance document has been created in accordance with the requirements of Chapter 4 of the adopted International Energy Conservation Code based on Climate Zone 5. If rating is Projected, I certify that the building design described herein is consistent with the building plans, specifications, and other calculations submitted with the permit application. If rating is Confirmed, I certify that the address referenced above has been inspected/tested and that the mandatory provisions of the IECC have been installed to meet or exceed the intent of the IECC or will be verified as such by another party.

Name:	Travis Marker	Signature:	rai llab	
Organization:	Energy Diagnostics Rater	Digitally signed:	10/8/18 at 3:13 PM	

Air Leakage Report

Property 4895 S 80 E WOLCOTTVILLE, IN 46795

4895 S 80 E 105634 18 Organization

Energy Diagnostics Rater

Travis Marker

Inspection Status Confirmed by field test

Builder

PETE'S CONSTRUCTION



General Information

Conditioned Floor Area [sq. ft.]	3,723
Infiltration Volume [cu. ft.]	43,467
Number of Bedrooms	4

Air Leakage

Measured Infiltration	1638 CFM50 (2.26 ACH50)
ACH50 (Calculated)	2.26
ELA [sq. in.] (Calculated)	90.1
ELA per 100 s.f. Shell Area (Calculated)	0.825
CFM50 (Calculated)	1638

Duct Leakage

	System 1
Leakage to Outdoors [CFM @ 25 Pa]	20.0
Leakage to Outdoors [CFM25 / 100 s.f.]	0.5
Leakage to Outdoors [CFM25 / CFA]	0.005
Total Leakage Test Type	No Test
Total Leakage [CFM @ 25 Pa]	N/A
Total Leakage [CFM25 / 100 s.f.]	N/A
Total Leakage [CFM25 / CFA]	N/A

Mechanical Ventilation

74.7
84.8